

ARMY STAGE



MANUAL DE USUARIO

- 1, Por favor, adquiera el gas CO2 como fuente de alimentación de poder.
- 2, Conecte el tanque con la manguera al SUPER BLASTE.
- 3, Abra la tapa de la SUPER BLASTER y coloque el papel confeti. Y cierre duramente.
- 4, Para comenzar, abra primero la válvula de aire del tanque de CO2, a continuación, para que comience a disparar, abra el interruptor/ válvula de la SUPER BLASTER, instantáneamente comenzara el disparo.
- 5, PRECAUCION: Mantenga una cierta distancia de la máquina mientras está en funcionamiento. No toque cualquier parte dentro de la máquina. No mire en el embudo. Asegúrese de que la máquina no apunta a nadie directamente a menos de 1 metro.

-
- 1、 Please choose the CO2 gas as power gas.
 - 2、 Use high pressure connects tube shall machine with bottle to link.
 - 3、 Open the machine box put in confetti paper.
 - 4、 Please first open the CO2 bottle air pressure, then open the machine valve switch, this time confetti machine can instantaneous jet plentiful confetti paper
 - 5、 Caution: Keep a certain distance away from the machine while it is operating. Do not touch any part inside the machine. Do not look into the funnel. Make sure the machine doesn't do any harm to personnel.

Manual de la SUPER BLASTER de CO2

Power	Consumo	CO2 liquido o gas nitrógeno
Contral	Operación	manual
Height of Ejection	Alcance	8-10M
Weight(Kg)	Peso	28Kg